DART AEROSPACE LTD	Work Order:	22411
Description: Lug and Bracket	Part Number:	D3010-13/15/-17-
,		D3017-7
Dwg: D3016 Rev. A; D3017 Rev. A page 1	Qty:	30 ZQ Kits
		Page 1 of 2

Step	Location	Procec lure	Ву	Date	Qty
1	DC	Issue Tigging	<i>X</i>	N 79 11	20
		To be mad in multiples of 8.	1 (y	05.0R.14	0
2	MV /	Cut blanks: 1.53" x 1.50" (+/-0.010)		,	
'	/	Material: AISI 4/30N Sheet, 0.049" thick (M4130N-S049)			
1		Identify for D3016-17 Batch:			
3	MV/	Cut blanks: 7.90" x 4.070" (+/-0.010)			
١	1010	Material: AISI 4130N Sheet, 0.049" thick			,
1		(M4120N-S049)			
		Identify for D3016-13 Batch:			/
4/	MV	Cyft blanks: 2.580" x 2.580" (+0.010/-0.000)	7	<u> </u>	
		Material: AISI 4130N Sheet, 0.049" thick			
		/(M4130N-S049) /	/	/	
/	1 4	Identify for D3016-15 Bateh:			
5	MV	Cut (12) D3017-7 blanks per 8 Kits			
		Cut blanks: 4.200" x 3.180" (+/-0.010)]	
		Material: AISI 4130N Sheet, 0.049" thick			•
		(M4130N-S049)	W	ososlic	20
	(8.4) (<u> </u>	V	20
6	/MV	Machine D3016-15 as per Folio FA162 and Dwg D3016	. /	1	
	İ	Use Stack of 8			1
1	000	Inspect parts as they come off the CNC machine	/		-/-
//	QC2	Inspect parts as they come on the CNC machine			/.
8	MV /	Deburr / /			
9	9C5	Second check			
10/	100	Marchide D2010 12 as for Folio FA162 and Dwg D2016	-		-
10/	MV	Machine D3016-13 as/per Folio FA162 and Dwg D3016 Use/Stack of 8		/	
		Identify as D3016/13	, ·		4
/11	QC2	Inspect parts as they come off the CNC machine		/	
11	QC2	Anspect parts as they come on the GNO machine			·
12	MV /	Deburr / /			
			/		
13	QC5	Second check		//	
	10/	/ / / D2047 7 F-II- F0400 D2047			
14	MV	Machine D3017-7 as per Folio FA163 and Dwg D3017			.
		Use Stack of 6 34-1 Identify as D3017-7	17	Resolo	30
15	QC2	Inspect parts as they come off the CNC machine	7.7	han a	-50
13	402	mapeor parts as they come on the ONO machine	Sn	050228	O
16	MV	Deburr	1		
			4	05.03.01	30
17	QC5	Second check		05/03/01	20
10	CAZ	Griad D3016-17 radius as per Dwg D3016		75000	36
18	GA	Identify as D3016-17	/		
19	GA	Debut			
1	(

H:\Forms\Quality Assurance\Approved QA\IPPSHORT revA

MELEASEN 103.06.11 PF

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES								
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector			
						:				
							!			
					<u> </u> 					
					}					


NCR:		V	WORK ORDER NON-CONFORMANCE (NCR)									
		Description of NC		Corrective Action Section B		Verification	Approval Design Mgr	Approval				
DATE	STEP	Section A	Initial Design Mgr	Action Description Design Mgr	Sign & Date	Section C		Approval QC Inspector				
	-											
				·								
			-									
1												

Part No:	PAR #:	Fault Category: N	NCR:	Yes	No	DQA:	Date:
NOTE: Date & initial all entries		dige.		QA: N	/C C	osed:	Date:


DART AEROSPACE LTD	Work Order:	22411
Description: Lug and Bracket	Part Number:	D3016-13/-15/-17
		D3017-7 -
Dwg: D3016 Rev. A; D3017 Rev. A page 1	Qty:	20 Kits
		Page 2 of 2


Step	Location	Procedure	Bv	Date	Qty
20	QC5	Inspect work to Step 19	M	05/3h	30
21	GB	Form D3017-7 as per Dwg D3017 and D3016-13 as per Dwg D3016	2	05.03.01	30
22	QC5	Inspect work to Step 21	ΔΛ	05/03/0	30
23	GA	Identify and bag with light oil (Vactra oil No. 2) D3016-13 Oty: D3016-15 Oty: D3016-17 Oty: D3017-7 Oty:	W	05/03/a	30
24	AC	Parts to Stock and prorate cost of parts per Step 23 Cost / part_ 29, > 4	540	05.03.02	3 6
²⁵	DC	Close W/O Z6, 4/ Inspect Level 21	11	05.03.02	30

Rev	Date	Change		Revised By	Approved
Α	01.09.11	New issue		EC .	
В	03.05.09	Reformat	, * ·	KJ/RF	#



D3016-041 SEAT FRAME ASSEMBLY






COPYRIGHT @ 2001 BY DART AEROSPACE LTD.

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

01.05.18

DESIGN W	DRAWN BY	DART	DART AEROSPACE LTD. HAWKESBURY, ONTARIO, CANADA
CHECKED	APPROVED	DRAWING NO.	REV. A
#	91	D3016	SHEET 2 OF 3
DATE	,	MLE	SCALE

SEAT FRAME ASSEMBLY







DESIG	P	DRAWN BY	DART AEROSPACE L HAWKESBURY, ONTARIO, CANADA	TD
CHECK	(ED M	APPROVED	DRAWING NO.	REV. A
	#	4	D3017 s	HEET 1 OF 2
DATE			TITLE	SCALE
01.0	5.18		BACK FRAME ASSEMBLY	1:1
 Α		01.05.18	NEW ISSUE	

QTY	PART No.	DESCRIPTION	MATERIAL
Х	D3017-041	BACK FRAME ASSEMBLY	N/A
1	D3017-1	TUBE	AISI 4130N TUBE, Ø0.75 DIA x 0.049 WALL (M4130N-T0750W049)
2	D3017-3	TUBE	AISI 4130N TUBE, Ø0.75 DIA x 0.049 WALL (M4130N-T0750W049)
1	D3017-5	TUBE	AISI 4130N TUBE, Ø0.75 DIA x 0.049 WALL (M4130N-T0750W049)
3	D3017-7	LUG	AISI 4130N SHEET, 18 GAUGE (M4130N-S049)
2	D3017-11	END CAP	AISI 4130N SHEET, 18 GAUGE (M4130N-S049)

NOTES

- 1) WELD PER DART QSI 004
- 2) ON SHEET METAL PARTS, BREAK ALL UNMARKED CORNERS 0.020-0.040
- 3) FINISH: POWDER COAT GREY SANDTEX (REF. 4.3.5.6) PER DART QSI 005 4.3
- 4) ALL DIMENSIONS ARE IN INCHES.
- 5) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED.

UNCOMPETATION TO

SUDJECT NOTICE

SHOP COPY

WORK ORDER 87 R0.25 o. (TYP) 0.000 1.86 50.191 (2 PLS) 2.063 R0.375 2.500 BENDING DETAIL R0.44 R0.375 3.183 (TYP) 0.000 R0.015 Ø0.750 FLAT PATTERN D3017-11 END CAP PART IS SYMMETRIC ABOUT CENTERLINE

Copyright @ 2001 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

Job Costing Report

Dart Aerospace Ltd. Hawkesbury

Feb 14, 2005 07:34 am

Work Order No : 0022411 Project Name : D3016-17

Department Code: Project For : WK511 Burden Flags : NNNNNNN Work Order Type : Main WO Status : Open

Invoice State : Not Invoiced Main WO Number

Invoice Date : House Part Number: D3016-17 Invoice Number: Description : Gusset

Invoice Amount : 0.00 Manufactured : Yes

Amount Req'd: 20

Amount Done : Order Entry No: 0

: 02-11-05 OE Value 0.00 Start Date Est Finish Date : 03-03-05

Act Finish Date : Est Margin 0.000% Actual Margin : 0.000% Drawings Reqd : No

Ok for Approval :

\$0 Posted to Finished Goods Approval Rec'd

		Estimated	Actual	Var. %	Posted	To Post
=======================================	===	=========	========	=======	==========	=========
Material Cost	:	0.00	0.00	0.00	0.00	0.00
Engineering Hours	:	0.00	0.00	0.00		•
Engineering Cost	:	0.00	0.00	0.00	0.00	0.00
Production Hours	:	0.00	0.00	0.00		
Production Cost	:	0.00	0.00	0.00	0.00	0.00
Packaging Hours	:	0.00	0,.00	0.00		
Packaging Cost	:	0.00	0.00	0.00	0.00	0.00
OverHead Hours	:	0.00	0.00	0.00		
OverHead Cost	:	0.00	0.00	0.00	0.00	0.00
CNC Hours	:	0.00	0.00	0.00		
CNC ·	:	0.00	0.00	0.00	0.00	0.00
Misc. Hours	:	0.00	0.00	0.00	·	
Misc.	:	0.00	0.00	0.00	0.00	0.00
*		========	========	======		•
Burden	:	0.00	0.00	0.00		<u>.</u>
		========	========	======		
Total Cost	:	0.00	0.00	0.00		•
Margin	: '	0.000	0.000			
Selling Cost	:	0.00	0.00			

.*		Estimated	Actual	
Labour Hrs/Amount Done	:	0.00	0.00	
Profits/(Loss)	:	0.00	0.00	

•	\					
DART AEROSI	PACE LTD				Work Order:	22411
Description:					Part Number:	D3017-7
Inspection Dwg:	Rev:					Page 1 of 1
	FIRST	ARTICLE IN	SPECTIO	ON CHE	CKŁIST	
X First Article			Prototype			
Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
R.25		-25				
2.063		2.059				
2,500				\ \ \		^
Ø.191 2		19/				
		15				
	•					
	_ M					
·			4 4			
	·					
Weasured by:	20 0	udited by:	- Ind	Pr	ototype Approv	(31:
	(0578	Date:	nelan	20		ate: NA
	Change		10/04	46J L		sed by Approved
	Vew Issue				KJ/JI	